



STARTER MOTOR INSTALLATION

IMPORTANT INSTALLATION INFORMATION

This starter motor supersedes multiple part numbers dating back to 1986.

All vehicles built from 1986 through 5/20/94 used a .045-inch shim between the starter motor and the engine block. That .045-inch shim is not compatible with this improved starter and must not be installed.

Vehicles built 5/20/94 and later do not use the .045-inch shim and are not affected.

Also note: For all vehicles regardless of build date, if the original starter installation included a .015 inch shim (as required), that .015 inch shim must be reinstalled.

Failure to follow these instructions may cause damage to the starter, including cracking of the case of the starter.