IMPORTANT

Jeep CJ, YJ, TJ, Cherokee, Wrangler and Wagoneer 1974-1998 with a 6 cylinder engine Possible Flywheel Balance Problem..

We have found that after having the flywheel surfaced, the flywheel balance may be affected. The flywheel balance should be checked by a qualified balance shop and corrected if out of factory tolerance, prior to the reinstallation of the flywheel and new clutch assembly.

If the flywheel is out of balance, the CENTERFORCE® weight system may shift off center and cause engagement and/or release problems.





"NOTE" Centerforce tip sheets are for general reference only. Please refer to your owners manual for vehicle specifications.

IMPORTANT

193AM001 CENTERFORCE TECH. LINE (928) 771-8422 WWW.CENTERFORCE.COM