

ULTRA X-TUNER POWER PROGRAMMERDodge 6.7L Cummins Installation Instructions

1054851 Dodge 6.7L Cummins 2007½-2008

*** READ THIS MANUAL & DISCLAIMER COMPLETELY BEFORE INSTALLING THIS PRODUCT ***
Installation Manual P/N#: I1054851

UNLESS AN EO# IS LISTED, THIS PRODUCT IS LEGAL IN CALIFORNIA FOR RACING VEHICLES ONLY, WHICH MAY NEVER BE USED UPON A HIGHWAY.

TABLE OF CONTENTS

Pre-Installation	3
Module Layout	4
Installation	
Main Menu ScreenPreparing the Tuner for Programming	5 6
Measuring Tire Size Programming the Vehicle	
Returning To Stock	7
DTC Function (Diagnostic Trouble Code)	8
Idle Up Feature	9
Setting Screen Contrast / Backlight	9
Tuner Updates	9
Recovery Mode	10
Troubleshooting / Technical Support	11

Pre-Installation

Thank you for choosing BD Power's *Ultra X-Tuner*. The *Ultra X-Tuner* is set up specifically for your 2007½-2008 Dodge 6.7L Cummins Diesel. The Ultra X-Tuner houses specialized databases that contain optimally calibrated, individual vehicle application, performance programs which tune both the engine & transmission. The Ultra X-Tuner includes **Performance**, **Tow/Performance** and **Tow** tuning programs for stock vehicles. Selectable tire height (for correcting speedometer & shift points) is also available for use.

The Ultra X-Tuner includes the following features:

- Internet Updateable Supports web updates via BD's update site
- Built-In DTC Definitions No lookup manual needed
- Built-In Help Screens Reduces need for manual look-up
- USB Communications Connects to any PC (Windows XP/2000 or higher) with USB
- Customs Application Upgradeable Download Custom performance programs
- Multiple Tuning Levels User Selectable Tuning Types
- Increased User Options Allows users more control
- Ergonomically Designed Case Fits well in the hand
- Large, soft key Buttons For easy operation
- Permanently mounted cable No assembly required
- Backlight Screen Easy to view day or night.

There are three power programs available for this tuner:

POWER LEVEL	H.P.	TORQUE
	GAINED	GAINED
Performance	115hp	250 lbs-ft
Tow/Performance	65hp	185 lbs-ft
Tow	60hp	100 lbs-ft
Stock	0	0

Periodically your dealer may flash your truck's computer if there is an issue with your truck when it is in for servicing (or even if there isn't a problem). Therefore, you should always revert your truck back to stock before bringing it back to the dealer for ANY work, because if your dealer flashes a new program over the modified "tuned" program from the Ultra X-Tuner, then your tuner will have to be reflashed at our factory.

Module Layout



The layout of the BD Ultra X-Power tuner is pretty straightforward. The module consists of a graphical LCD display, 3 selection buttons (notice the relation to the placement on the screen) and an OBD-II communications cable, hardwired into the module.

Installation

Make sure that your vehicle is in the key off/engine off position before you plug in the Ultra X-Tuner.

Connect the communications cable that came with the downloader into the top of the Ultra X-Tuner and the other end into the OBD II port (see diagram above). The OBD II port is the diagnostic port located underneath the dash on the driver's side of the vehicle.



OBDII Port

Main Menu Screen

The downloader will boot up with a BD logo and proceed to the main menu. From here you can decide which option you would like to select:

TUNER SETUP – Displays current firmware/database info numbers for the tuner, changes contrast & backlight options.

TUNING – Select this option to download a power program, or to adjust transmission shifting or to return the program to stock.

DIAGNOSTICS – Select this option to view and erase diagnostic trouble codes.

PEF Tuner Setup OM Tunine Diaenostics NEXT ENTER

The layout of the main menu is as follows:

- Tuner Setup
 - About
 - Set Screen Contrast
 - Set Screen Backlight
- Tuning
 - o Read Vehicle
 - Change Settings
 - View Settings
 - o Program Vehicle
- Diagnostics
 - Diagnostic Codes (Read/Clear DTC's)
 - o Data Logging

Preparing the Tuner for Programming

Select the **Tuning** option from the main menu with the enter key as described on the tuner.

Select **Read Vehicle**. This option will read the stock engine and transmission program currently loaded into your PCM and save a copy into the tuner. This information will be used to revert your truck back to stock in the future if desired. When the tuner loads the "Read Vehicle" menu, select **Read Stock.**



This option will take roughly 5 minutes to complete.

Once complete, choose the **Change Setup** option. In the Change Setup menu, select **Power Level**. From here you can choose your power level — Tow / Tow-Performance / Performance. Select "Save" once you have chosen your power level, and then press "Exit", or,



If you wish to change the tire size options, then read the section below. Or, if you wish to program with just these settings, then select **Program Vehicle** and press the Enter key. This will begin the tuning process.

Measuring Tire Size

When using the tuner to input a bigger-than-stock size tire (for fixing erroneous speedometer values), then your tire must be measured for the proper calculations to be used.

Measure the tire vertically with a tape measure. It may help to have a tool with a flat edge (i.e. a ruler) resting on top of your tire for a more accurate reading. Measure your vehicle's tire (**in inches**) and round it up to the nearest quarter of an inch. When measuring the tire, both the tire and rim must be included.

This option can be found in the **Change Setup / Options / Tire Height** menu.

Programming the Vehicle

Once you have finished with your selections exit the menu and you will be taken back to the main screen.

Once you have finished with your selections exit the menu and you will be taken back to the main screen.

To confirm your selections you can scroll down to **View Settings**.

Otherwise if you are reading to program, scroll down to **Program Vehicle**. Press enter once your there and follow the on screen prompts to program the vehicle.



Returning To Stock

This option is for when you are taking your vehicle in for a diagnostic service, or just want your settings to be back to the OEM specifications.

Plug in the Ultra X-Tuner and select the **Tuning** option from the main menu, and then select **Change Setup**, and then select **Power Level**.

This will bring up the power selection menu. On the displayed list, select **Stock** and hit Enter.

The tuner will then ask you to confirm that you would like to return to stock. Hit Yes if you would like to continue. At this point, it will re-load your stock program back into your truck.



Once you have finished with your selections exit the menu and you will be taken back to the main screen.

To confirm your selections you can scroll down to **View Settings**.

Otherwise if you are reading to program, scroll down to **Program Vehicle**. Press enter once your there and follow the on screen prompts to program the vehicle.



When the load is finished, the Ultra X-Tuner will have returned the vehicle to the stock power level, as well as the transmission shift patterns.

DTC Function (Diagnostic Trouble Code)

The DTC function will display all diagnostic trouble codes set on your vehicle. This function will also allow you to read and erase trouble codes from your vehicle's ECU.

Read DTCs reads and displays Diagnostic Trouble Codes from the connected vehicle. **Clear DTCs** clears current Diagnostic Trouble Codes from the connected vehicle.

Both options are for live vehicle diagnostics. An active vehicle connection to the tuner is required. Vehicle DTC's, if present, will be displayed along with a full text description, when available.

To access this menu, select **Diagnostics** at the main menu and hit Enter.



If you want to read the DTC's currently in your system, select **Read DTCs** and then hit Enter.

If you want to Clear DTCs currently in your system, select **Clear DTCs** and then hit Enter.



Re-occurring Diagnostic Trouble Codes you may encounter:

CODE	Definition	Reason
P0603	Internal Control Module CAM Error	Both codes are time delayed codes
<u>P1000</u>	OBDII Monitor Checks Not Complete – More Driving Required)	which may erase over time, but cannot be erased by the Ultra X-Tuner.

Idle Up Feature

This feature can be used to enable or disable Idle Up. When Idle Up is enabled, the engine idle speed can be adjusted up or down to a desired level. The adjustment is done in the vehicle using switches, such as the cruise control increase switch. Generally, adjusting the engine idle speed is used to warm up engines in colder temperatures or to provide additional power for external PTO devices.

This function can be found in the **Advanced Features Menu**.

Setting Screen Contrast / Backlight

The Ultra X-Tuner's screen contrast and backlight level can be changed to the user's preference. Select **Tuner Setup** from the main menu.

Select either "Set Contrast" or "Set Backlight", depending on which option you would like to change.



Tuner Updates

If the dealer flashes a new program onto your computer that is newer than the database in the tuner, then the tuner will have to be updated. This is done by visiting http://xtuner.bd-power.com/ through your preferred internet browser and clicking on the "Ultra X-Tuner" link. Follow the screen prompts to install and update the software.

Recovery Mode

In the event of a status message during a programming sequence, the Ultra X-Tuner will attempt to recover the vehicle to the original stock program. It is necessary to carefully follow the screen prompts, possibly requiring multiple "Ignition OFF" and "Ignition ON" sequences to correctly return the vehicle to stock settings.

When the recovery is completed, your vehicle is returned to factory stock. You are now able to start your vehicle normally. You may not attempt to use the Ultra X-Tuner to program your vehicle again or to program another vehicle (the tuner is now reset and not locked to a vehicle). Follow the on-screen prompts. In the event that recovery is unsuccessful, or fo any reason the Ultra X-Tuner fails to complete its programming cycle, a status message will be displayed on the unit. Please make note of the message displayed and contact BD Diesel Performance technical support department.

Simply follow the on-screen prompts from the tuner to go through recovery mode.

Troubleshooting / Technical Support

"Vehicle File is Not Stock ... Call BD Power! Use

Code #E-43."

Complaint: Solution:

Ultra X-Tuner screen is blank when plugged into 1. The diagnostic port may share power with the the vehicle. cigarette lighter fuse. Check the owner manual for location and replace if it is blown. 2. Check the pin connectors in the OBDII port. Make sure that none of the pins have been pushed out of the connector body. (Note: Typically not all connector pins are present). 3. Try plugging the tuner into another supported vehicle and verify the tuner status. Ultra X-Tuner flashes "Tuner Requires an The Ultra X-Tuner does not have the necessary Update" message after visit to the dealer and/or calibration files that coincide with your truck's reflash. new update, so an update for your tuner is necessary. Refer to the section "updating your tuner" on page xx for updating instructions. Unsupported application. Check the year, model and engine model to verify that the Ultra X-Tuner being usedi s If the vehicle or engine type is not currently supported by the Ultra X-Tuner, the following error correct for the application. If not, return it to the dealer that it was purchased from for the correct message may be displayed: tuner. If the application matches up, then phone "This application is currently unsupported. Call BD POWER for an RMA number to send in the us if incorrect, Call BD POWER and use Code #Etuner for inspection. 36." Non-Stock File Application. This may be because another programmer has If the Ultra X-Tuner has checked your stock file and been previously used to reprogram the vehicle. cannot match it to a stock file, the following message The vehicle that this tuner is going on MUST be will be displayed: stock before trying to program with the Ultra X-Tuner.

Locked VIN Number.

If the Ultra X-Tuner programming is in a vehicle, then the tuner is "locked" to that vehicle – meaning that no other vehicle can be programmed with that tuner. If you try and use the programmer you will receive this message:

"Locked VIN is mismatched! Not the original vehicle / program. Call BD POWER! Use Code #E-37."

Return the original vehicle back to stock before using the Ultra X-Tuner on another vehicle, or purchase an additional Ultra X-Tuner for use on a second vehicle.

Not original Program ID.

If the Ultra X-Tuner is "VIN locked" to a vehicle and that vehicle has been updated at the dealership to a different Box Code (ID Number) without first using the tuner to return the vehicle to stock, the following message will be displayed:

"Not the original Program ID. Not the Original Vehicle/Program. Call BD POWER! Use Code #E-38."

The Ultra X-Tuner can only be unlocked if it is able to return the "Vin Locked" vehicle to stock. Since a dealership has replaced the Ultra X-Tuner's programming in the truck with updated stock tuning, you will need to update your tuner online with a re-flash.

Checksum Error.

If the Ultra X-Tuner is "VIN locked" to a vehicle and that vehicle has been updated at the dealership to the same Box Code (ID Number) without first using the tuner to return the vehicle to stock, the following message will be displayed:

"Not the original Program Checksum. Not the Original Vehicle/Program. Call BD POWER! Use Code #E-39."

The Ultra X-Tuner can only be unlocked if it is able to return the "Vin Locked" vehicle to stock. Since a dealership has replaced the Ultra X-Tuner's programming in the truck with stock tuning, you will need to update your tuner online with a re-flash.

Upload Error.

If the Ultra X-Tuner cannot detect if the ignition is in the on position, the following message will be displayed:

"Problem with uploading! Please retry. Call BD POWER! Use Code #E-XX." (XX= a two digit number).

Make sure that the ignition is ON (with the vehicle OFF). Retry again. It is possible that your vehicle's battery charge is low. Please check and correct, if necessary.

Ignition ON Error.

If the Ultra X-Tuner cannot detect that the ignition is in the ON position, the following messages will be displayed:

Make sure that the ignition key is turned completely forward in the ON position. (DO NOT START THE VEHICLE).

"Cannot Detect Ignition On. Please Retry. Call BD POWER! Use Code #E-31."

Communications Error

If the Ultra X-Tuner loses communication, the following message will be displayed:

"Communications Error!!! Please retry. Call BD POWER! Use Code #E-XX."

Make sure that the ignition is ON (but DO NOT start the vehicle!). Retry again. It is possible that your vehicle's battery charge is low. Please check and correct if necessary. If it still fails, then contact BD Power. The Ultra X-Tuner will have to be returned to BD.

If you encounter any other problems with this product, or have technical questions about it, please phone the BD Diesel Performance Technical Hotline at (800) 887-5030 between 8:00am – 5:00pm, Monday to Friday, Pacific Standard Time (PST). As an alternative, you can also post on our technical forum located at http://bd-power.com/forum.

