



Crown Automotive Sales Co., Inc.

Revision Notice

Replaces Part No: 83501167MK

The caliper bushing that isolated the caliper pin from the rubber boot from the factory has been removed from this kit. We now include (2) packets of white lithium grease to lubricate the pin inside the boot.

We have found replacing the factory caliper bushing with grease results in smoother caliper operation.

While every attempt is made to ensure that the information contained in these instructions are correct, no liability can be accepted by the authors for loss, damage or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co., Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions and equipment should be used in every procedure.