

IMPORTANT
Holley Wide-band Oxygen Sensor Addendum

In early 2005, Holley updated their wide-band oxygen sensor controllers and sensors from a 1st Generation version to a 2nd Generation version. Although performance of both units is identical, the sensor and controllers are different and are not cross-compatible. This means a 1st Gen sensor can ONLY be used with a 1st Gen controller and a 2nd Gen sensor can ONLY be used with a 2nd Gen controller. Mixing the two will permanently damage the sensor.

To insure that this does not occur, the cable and connector design was changed between the two. The following shows the differences in the controller and sensors:

1st Gen Controller – Oxygen sensor cable was part of the controller and was non-removable.

2nd Gen Controller – The oxygen sensor cable is a 4 foot cable that is separate from the controller.

1st Gen Oxygen Sensor – The connector only plugs into a 1st Gen Controller. It can NOT be plugged into a 2nd Gen cable.

2nd Gen Oxygen Sensor - The connector only plugs into a 2nd Gen Cable. It can NOT be plugged into a 1st Gen cable.

199R10346
Date: 1-24-05

IMPORTANT
Holley Wide-band Oxygen Sensor Addendum

In early 2005, Holley updated their wide-band oxygen sensor controllers and sensors from a 1st Generation version to a 2nd Generation version. Although performance of both units is identical, the sensor and controllers are different and are not cross-compatible. This means a 1st Gen sensor can ONLY be used with a 1st Gen controller and a 2nd Gen sensor can ONLY be used with a 2nd Gen controller. Mixing the two will permanently damage the sensor.

To insure that this does not occur, the cable and connector design was changed between the two. The following shows the differences in the controller and sensors:

1st Gen Controller – Oxygen sensor cable was part of the controller and was non-removable.

2nd Gen Controller – The oxygen sensor cable is a 4 foot cable that is separate from the controller.

1st Gen Oxygen Sensor – The connector only plugs into a 1st Gen Controller. It can NOT be plugged into a 2nd Gen cable.

2nd Gen Oxygen Sensor - The connector only plugs into a 2nd Gen Cable. It can NOT be plugged into a 1st Gen cable.

199R10346
Date: 1-24-05