



OMIX-ADA, Inc.




11651.07 : 2 Door Left/Right Rear Body
11651.09 : 4 Door Left/Right Rear Body


JEEP® JK BODY ARMOR

Contents:

- (1) Left Rear Body Armer



- (1) Right Rear Body Armer




Required Tools:


- Phillips screwdriver
- Socket Driver
- 7 mm. Socket
- Flathead screwdriver (Only for 2 Door)

1. Remove the licence plate using phillips screwdriver.
(For 2 Door using a Flathead screwdriver)

2. Remove the licence plate holder using a socket driver and 7mm. socket.



3. Remove the driver side and passenger side tail light using a phillips screwdriver.



OMIX-ADA® TECHNICAL SUPPORT

PHONE: M-F 8am - 5pm EST 1-800-449-6649 | EMAIL: techsupport@omix-ada.com

FOR WARRANTY INFORMATION VISIT: www.Omix-Ada.com



OMIX-ADA, Inc.




11651.07 : 2 Door Left/Right Rear Body

11651.09 : 4 Door Left/Right Rear Body

JEEP® JK BODY ARMOR


4. Clean surface with isopropyl alcohol (rubbing alcohol).



5. Apply 3M® Adhesive Promoter 06396 to mounting surface. Avoid areas that tape will not contact. Allow 90 seconds for Adhesive Promoter to dry before proceeding.

Note: For best results, install within 10 minutes of installing Adhesive Promoter.

6. Test fit Body Armor to the vehicle before removing plastic liner from mounting tape. This will aid in aligning the item before adhesion.




7. Remove only enough plastic liner to be easily gripped when item is installed.

Note: The plastic liner of the shorter tape sections may need to be fully removed before installing.

8. Install item in proper mounting position while keeping partially removed liner ends accessible.

9. Firmly hold the Body Armor in proper mounting position while pulling the exposed plastic liner to completely remove. Maintain pressure on installed item for 30 seconds to ensure proper contact. Full adhesion occurs within 24 hours of application.



NOTICE Areas where promoter may be visible can be cleaned with acetone solvents or methylethylketone (MEK). See promoter manufacturer for further detail.

CAUTION Solvents can cause cosmetic damage to plastic surfaces. See promoter manufacturer for further detail.

10. Reinstall the licence holder, licence plate and tailgate lights.

