

If you have any comments or concerns,
please feel free to contact our
customer service department at:
Toll-free: 1-800-835-0438
OR
Email: info@gofia.com

SEAT COVERS
BY



FEATURING

SUPER-GRIP®

**THE SLIP RESISTANT FASTENING SYSTEM
INSTALLATION INSTRUCTIONS**

FOR

TR49-31, OE39-31, SL69-31, SP89-31

Thank you for purchasing one of our fine quality products. Your seat cover is engineered from high quality materials and designed with precision to give you a long-lasting, well-adjusted fit.

INSTRUCTIONS:

DRIVER'S SIDE – ONE PIECE BUCKET SEAT COVER

A) BACKREST COVER –

- 1) Remove head rest (see note)
- 2) Slip cover over backrest
- 3) Pull down firmly over backrest
- 4) Recline backrest

- 5) Pass the straps attached to center flap through crevice
- 6) Move backrest to upright position
- 7) Replace headrest (see note)

B) CUSHION COVER

- 1) Move seat to most forward position
- 2) Center cushion cover on seat
- 3) Pull straps to front from underneath the seat at crevice
- 4) Buckle to the front of the seat

- 5) Pass side straps to the back of the seat and buckle to back flap of backrest
- 6) Adjust all straps and buckles to equalize tension for a uniform fit

PASSENGER SIDE – TWO PIECE BUCKET SEAT COVER

A) BACKREST COVER –

- 1) Remove head rest (see note)
- 2) Open zipper
- 3) Slip cover over backrest and pull down firmly

- 4) Close zipper (see note)
- 5) Replace headrest (see note)

B) CUSHION COVER –

- 1) Center cover on seat
- 2) Pass the front strap under seat and buckle to back flap

- 3) Pass side straps around back of seat and buckle
- 5) Adjust straps and buckles to equalize tension

NOTES:

1) SELF-LOCKING SUPER-GRIP® BUCKLE:



3) ZIPPERS:

- For ease in installation the zipper is longer than the cover.
- Tuck excess zipper under cover

2) HEAD REST REMOVAL:

- A) - Insert paper clip into holes at base to release
- Lift off

OR

- B) - Push in side release buttons
- Lift off

(If unable to remove consult dealership)



4) RE-INSTALLATION OF HEADRESTS

- A) Ensure pre-cut holes in seat cover align with holes in base.
B) Replace headrests

WARNING: NEVER INSTALL SEAT COVERS ON SEATS WITH BUILT-IN AIRBAGS AS THIS MAY INTERFERE WITH THE PROPER DEPLOYMENT OF THE AIR BAGS WHICH COULD RESULT IN SERIOUS INJURY.



Fia Inc. Winnipeg, Canada R3L 0N3 Telephone (204) 475-0515 Toll-Free: 1-800-835-0438
Fax: (204) 284-8246 E-Mail: info@gofia.com Website: www.gofia.com

04-28-08