


## INSTALLATION INSTRUCTIONS MECHANICAL SPEEDOMETER

PART NUMBER P5155706



## Mounting



## Installation

- 1. Cut a 3-3/8" hole in the dashboard for the speedometer.
- 2. To connect the speedometer cable:
  - A. If existing speedo cable in vehicle is being used, connect it to the cable input on back of speedo. Make sure cable fits properly into .104" sq. female cable input before tightening.
  - B. If a new speedo cable is required, purchase a "custom made" cable from an auto parts store or speedometer specialty shop. The cable input on back of speedometer accepts only .104" sq. male drive. Make sure connections fit properly before tightening.
- 3. Drill a <sup>11</sup>/<sub>16</sub>" diameter hole in engine firewall where cable will be routed. Route cable from speedo through dash, through firewall and connect to transmission take-off. Use the rubber grommet provided (slit) to support the cable in the firewall. Make sure all connections fit properly before tightening.
- 4. Secure the speedometer in the dashboard by using the brackets, nuts and lock washers provided.

5. For lighting connect the white wire to dash lighting circuit (or +12 volts). Connect black wire to chassis ground.

**Specifications:** This speedometer is set up for a 1:1 drive ratio (60 MPH at 1,000 RPM input to speedometer head) and a 5/8" x 18 threaded cable input that requires a .104" sq. male drive. If vehicle tire size and/or rear-end differential are not stock (original), a different driven gear in the transmission may be required for speedo accuracy. If a change in the driven gear is made, you very likely will have to change the drive gear in the transmission to maintain the proper gear tooth engagement. Another approach is to use a "correcting ratio" drive joint to adjust the speedometer input to 60 MPH at 1,000 RPM. If one is needed, the appropriate ratio can be easily determined by comparing your speedometer reading against another car having an accurate speedometer and dividing the speeds. (Accurate speed ÷ Your speed = Ratio needed) Auto parts stores or speedometer specialty shops carry "correcting ratio" drive joints.

NOTE: The clear lens on your speedometer may be made of acrylic. To prevent scratching use a mild, soapy solution and soft cloth to clean. Wipe lightly.

## MOPAR PERFORMANCE PARTS ARE SOLD "AS IS," WITHOUT ANY WARRANTY WHATSOEVER.

Implied warranties, including warranties of merchantability or fitness for a particular purpose, are excluded. The entire risk as to quality and performance of such parts is with the buyer. Should such parts prove defective following their purchase, the buyer and not the manufacturer, distributor or retailer, assumes the entire cost of all necessary servicing or repair. Chrysler, Dodge, and Jeep® vehicle and parts warranties are voided if the vehicle or parts are used for competition or if they fail as a result of modification.