



**ADDENDUM TO INSTRUCTIONS 199R-9881**  
AFFECTING  
**HOLLEY CARBURETOR MODEL #'S**

**0-80450**  
**0-80451**  
**0-80454**

**VACUUM HOSE ROUTING**

Due to changes in vacuum sources on these carb models, the hose routing has changed.

**The Cannister Purge Port/Hose #4 now needs to be "T'd" into the Ported EGR Signal Port/Hose # 2.**

A full listing and diagrams of hose connections can be found in the instruction sheet. All other connections are per instructions.

Holley Performance Products  
P.O. Box 10360  
Bowling Green, KY 42102-7360

Technical Service: 270-781-9741  
Fax: 270-781-9772

199R-10252  
Date: 4-23-01



**ADDENDUM TO INSTRUCTIONS 199R-9881**  
AFFECTING  
**HOLLEY CARBURETOR MODEL #'S**

**0-80450**  
**0-80451**  
**0-80454**

**VACUUM HOSE ROUTING**

Due to changes in vacuum sources on these carb models, the hose routing has changed.

**The Cannister Purge Port/Hose #4 now needs to be "T'd" into the Ported EGR Signal Port/Hose # 2.**

A full listing and diagrams of hose connections can be found in the instruction sheet. All other connections are per instructions.

Holley Performance Products  
P.O. Box 10360  
Bowling Green, KY 42102-7360

Technical Service: 270-781-9741  
Fax: 270-781-9772

199R-10252  
Date: 4-23-01