



**P/N 558-304  
HEI ADAPTER HARNESS**

The use of this adapter requires that the software and firmware versions be at the following levels or higher:

**Software – Version 1.1.5 and higher.**

**Firmware – Version 279 or numerically higher.**

If you have earlier software and firmware versions, you can download both at Holley's website. Use the following web address:

<http://www.holley.com/TechService/Library.asp>

Instructions on updating the firmware are found in the software's Help/Instructions section under "Updating Firmware".

**199R10557**

**Date: 5-27-10**